

Methods of test for

Footwear and footwear materials

Part 1. Adhesives

Section 1.3 Preparation of test assemblies using adhesives (other than hot melt adhesives) for heat resistance (creep) and peel tests

NOTE. It is recommended that this Section should be read in conjunction with BS 5131 : Part 0, published separately.

Méthodes d'essais des chaussures et matériaux pour chaussures
Partie 1. Colles
Section 1.3 Préparation des assemblages d'essai collés (à colles autres que thermofusible autoadhésive) pour essais de résistance (fluage) et de pelage

Prüfung von Schuhwerk und Schuhwerkstoffen
Teil 1. Klebstoffe
Abschnitt 1.3 Herstellung von Probekörpern mit Klebstoff (außer Schmelzklebstoff) zur Prüfung der Wärmebeständigkeit und des Schälwiderstandes

Foreword

This Section of BS 5131 has been prepared under the direction of the Textiles and Clothing Standards Policy Committee. It supersedes BS 5131 : Subsection 1.1.3 : 1976, which is withdrawn.

Compliance with a British Standard does not of itself confer immunity from legal obligations.