

Stairs, ladders and walkways –

Part 2: Code of practice for the design of helical and spiral stairs

ICS 91.060.30

Confirmed December 2011

Committees responsible for this British Standard

The preparation of this British Standard was entrusted by the Elements and Components (of Diverse Materials) for Buildings Standards Committee (ECB/-) to Technical Committee ECB/2 upon which the following bodies were represented:

- Aluminium Federation
- British Woodworking Federation
- Concrete Society
- Department of Health and Social Security
- Department of the Environment, Building Research Establishment, Princes Risborough Laboratory
- Department of the Environment, Housing and Construction
- Energy Industries Council
- Engineering Equipment and Materials Users' Association
- Greater London Council
- Health and Safety Executive
- Incorporated Association of Architects and Surveyors
- Institution of Mechanical Engineers
- Institution of Structural Engineers
- Joinery Managers' Association Ltd.
- London Transport Executive
- Royal Institute of British Architects
- Scottish Development Department
- Spiral Stair Manufacturers' Association

The following bodies were also represented in the drafting of the standard, through subcommittees and panels:

- Institution of Building Control Officers
- Co-opted members

This British Standard, having been prepared under the direction of the Elements and components (of Diverse materials) for Buildings Standards Committee, was published under the authority of the Board of BSI and comes into effect on 31 January 1984

© BSI 2009

The following BSI references relate to the work on this standard:
Committee reference ECB/2
Draft for comment 82/12150 DC

ISBN 978 0 580 67560 7

Amendments issued since publication

Amd. No.	Date of issue	Comments
6076	July 1989	Indicated by a sideline in the margin
	July 2008	Corrigendum to replace poor quality figures
C2	March 2009	Table 2: "Minimum outer going" corrected to "Maximum outer going" This corrigendum corrects an error that appears in some versions of this standard only.
C3	June 2009	Corrigendum to replace incorrect figures including keys and to correct equation in 5. 2