

This Standard is confirmed.  
See the BSI Catalogue for details.  
*June 1998*

# Installation of factory-made chimneys to BS 4543 for domestic appliances —

## Part 4: Recommendations for installation design and installation

# Committees responsible for this British Standard

The preparation of this British Standard was entrusted by Technical Committee B/506, Chimneys, to Subcommittee B/506/5, Chimneys and their components having inner linings of metal, upon which the following bodies were represented:

- Association of British Solid Fuel Appliances Manufacturers
- British Coal Corporation
- British Combustion Equipment Manufacturers' Association
- British Flue and Chimney Manufacturers' Association
- British Gas plc
- British Precast Concrete Federation Ltd.
- British Steel Industry
- Building Services Research and Information Association
- Clay Pipe Development Association Limited
- Department of the Environment
- Department of the Environment (Construction Directorate)
- Health and Safety Executive
- Institute of Domestic Heating and Environmental Engineers
- National Association of Plumbing, Heating and Mechanical Services Contractors
- National Federation of Master Steeplejacks and Lightning Conductor Engineers
- National House-building Council

The following bodies were also represented in the drafting of the standard, through subcommittees and panels:

- Department of the Environment (Building Research Establishment)
- Institute of Vitreous Enamellers
- Real Fire Association
- Society of British Gas Industries
- Vitreous Enamel Development Council

This British Standard, having been prepared under the direction of Technical Committee B/506, was published under the authority of the Standards Board and comes into effect on 15 July 1992

© BSI 18 March 2003

The following BSI references relate to the work on this standard:  
Committee reference B/506/5  
Draft for comment 89/13385 DC

ISBN 0 580 20583 5

## Amendments issued since publication

| Amd. No.             | Date          | Comments             |
|----------------------|---------------|----------------------|
| 14210<br>Corr. No. 1 | 18 March 2003 | Change to <b>9.1</b> |
|                      |               |                      |
|                      |               |                      |
|                      |               |                      |