

Automotive windscreen repair — Code of practice

ICS 43.040.60

Committees responsible for this British Standard

The preparation of this British Standard was entrusted to Technical Committee AUE/10, Safety glass for land transport, upon which the following bodies were represented:

- Association of British Glass Repair Operators
- Automobile Association
- British Plastic Federation
- Consumer Policy Committee of BSI
- Department of the Environment, Transport and the Regions — Central Transport Group
- Flat Glass Manufacturers' Association
- Automotive Glazing Executive (Glass and Glazing Federation)
- National Caravan Council Limited
- Society of Motor Manufacturers and Traders Limited
- Transport Research Laboratory
- Windscreen and Glass Repairers' Association
- Windscreen Repair Equipment Manufacturers and Suppliers Association

This British Standard, having been prepared under the direction of the Engineering Sector Committee, was published under the authority of the Standards Committee and comes into effect on 15 December 1998

© BSI 03-1999

First published as BS AU 242 November 1991

The following BSI references relate to the work on this standard:
Committee reference AUE/10
Draft for comment 98/706290 DC

ISBN 0 580 28209 0

Amendments issued since publication

Amd. No.	Date	Text affected
10419	March 1999	Indicated by a sideline