

Liquid pumps and pump units — Noise test code — Grade 2 and grade 3 of accuracy

The European Standard EN 12639:2000 has the status of a
British Standard

ICS 17.140.20; 23.080

National foreword

This British Standard is the official English language version of EN 12639:2000, including corrigenda November 2000 and September 2004.

The UK participation in its preparation was entrusted by Technical Committee MCE/6, Pumps and pump safety, to Subcommittee MCE/6/3, Testing of pumps, which has the responsibility to:

- aid enquirers to understand the text;
- present to the responsible international/European committee any enquiries on the interpretation, or proposals for change, and keep the UK interests informed;
- monitor related international and European developments and promulgate them in the UK.

A list of organizations represented on this subcommittee can be obtained on request to its secretary.

Cross-references

The British Standards which implement international or European publications referred to in this document may be found in the *BSI Catalogue* under the section entitled “International Standards Correspondence Index”, or by using the “Search” facility of the *BSI Electronic Catalogue* or of British Standards Online.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

Compliance with a British Standard does not of itself confer immunity from legal obligations.

Summary of pages

This document comprises a front cover, an inside front cover, the EN title page, pages 2 to 25 and a back cover.

The BSI copyright notice displayed in this document indicates when the document was last issued.

This British Standard, having been prepared under the direction of the Engineering Sector Committee, was published under the authority of the Standards Committee and comes into effect on 15 May 2000

© BSI 29 September 2004

Amendments issued since publication

Amd. No.	Date	Comments
13030 Corrigendum No. 1	August 2001	Corrects equations in Figures 5 and 6
15369 Corrigendum No. 2	29 September 2004	Corrects Figure B.1