
**X and gamma reference radiation for
calibrating dosimeters and doserate
meters and for determining their response
as a function of photon energy —**

Part 3:

Calibration of area and personal dosimeters
and the measurement of their response as a
function of energy and angle of incidence

*Rayonnements X et gamma de référence pour l'étalonnage des dosimètres
et des débitmètres et pour la détermination de leur réponse en fonction de
l'énergie des photons —*

*Partie 3: Étalonnage des dosimètres de zone (ou d'ambiance) et individuels
et mesurage de leur réponse en fonction de l'énergie et de l'angle
d'incidence*



Contents

1 Scope	1
2 Normative references	1
3 Definitions	2
3.1 Quantities and units	2
3.2 Calibration factor and response determination.....	3
4 Procedures applicable to all area and personal dosimeters	5
4.1 General principles.....	5
4.2 Methods for the determination of the calibration factor and the response.....	9
5 Particular procedures for area dosimeters	12
5.1 General principles.....	12
5.2 Quantities to be measured.....	12
5.3 Conversion coefficients	12
6 Particular procedures for personal dosimeters.....	22
6.1 General principles.....	22
6.2 Quantities to be measured.....	23
6.3 Experimental conditions	23
6.4 Conversion coefficients	25
7 Presentation of results	35
7.1 Records and certificates	35
7.2 Statement of uncertainties.....	36
Annex A (informative) Additional information.....	37
Bibliography	46

© ISO 1999

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization
Case postale 56 • CH-1211 Genève 20 • Switzerland
Internet iso@iso.ch

Printed in Switzerland