

TECHNICAL REPORT

ISO
TR 9326

First edition
1989-07-15

Implants for surgery — Partial and total hip joint prostheses — Guidance for laboratory evaluation of change of form of bearing surfaces

*Implants chirurgicaux — Prothèses partielle et totale de hanche — Recommandations
pour l'évaluation en laboratoire du changement de forme des surfaces articulaires*



Reference number
ISO/TR 9326 : 1989 (E)

Contents

	Page
Foreword	iii
Introduction	iv
1 Scope	1
2 Preparation of test specimens	1
3 General recommendations for measuring wear	1
4 Measurement of wear by weighing	2
5 Measurement of wear by means of dimensional changes	3
6 Measurement of wear by thin layer activation	4
Tables	
1 Summary of methods of estimating dimensional changes	4
2 Thin layer activation of materials for hip prostheses	5
Annex	
A Bibliography	6