

Specification for

Matchboarded wooden door leaves for external use

UDC 674 – 4:69.028.1:674.214:692.817.1:691.178:[696.134.5.002.2]:(083.71)

Confirmed December 2011

Committees responsible for this British Standard

The preparation of this British Standard was entrusted by the Timber Standards Committee (TIB/-) to Technical Committee TIB/23, upon which the following bodies were represented:

- Association of Builders Hardware Manufacturers
- British Furniture Manufacturers' Federation
- British Lock Manufacturers' Association
- British Standards Society
- British Woodworking Federation
- Department of Health and Social Security
- Department of the Environment [Building Research Establishment (Fire Research Station)]
- Department of the Environment [Building Research Establishment (Princes Risborough Laboratory)]
- Department of the Environment [Construction Industry Directorate (Building Regulations)]
- Department of the Environment (Property Services Agency)
- Fibre Building Board Organization (FIDOR)
- Fibre Cement Manufacturers' Association Limited
- Flat Glass Manufacturers' Association
- Guild of Architectural Ironmongers
- Gypsum Products Development Association
- Institute of Carpenters
- Institution of Fire Engineers
- Intumescent Fire Seals Association
- Joinery Managers' Association Ltd.
- London Housing Consortium
- Royal Institute of British Architects
- Timber Research and Development Association

This British Standard, having been prepared under the direction of the Timber Standards Committee, was published under the authority of the Board of BSI and comes into effect on 30 November 1988

© BSI 03-1999

First published as BS 459, June 1932
First revision (War emergency series), May 1941
Second revision (War emergency series), August 1942 (withdrawn 1944)
Third revision as BS 459-4, September 1951
Fourth revision, February 1965
Fifth revision, November 1988

The following BSI references relate to the work on this standard:
Committee reference TIB/23
Draft for comment 86/10538 DC

ISBN 0 580 16483 7

Amendments issued since publication

Amd. No.	Date of issue	Comments
8737	July 1995	Indicated by a sideline in the margin