

Electrical apparatus for potentially explosive atmospheres — Type of protection “n”

The European Standard EN 50021:1999 has the status of a
British Standard

ICS 29.260.20

National foreword

This British Standard is the English language version of EN50021:1999. It supersedes BS 6941:1988 and BS 5000-16:1997 which are withdrawn.

The UK participation in its preparation was entrusted by Technical Committee GEL/31, Electrical apparatus for explosive atmospheres, to Subcommittee GEL/31/14, Types of protection “e” and “n”, which has the responsibility to:

- aid enquirers to understand the text;
- present to the responsible international/European committee any enquiries on the interpretation, or proposals for change, and keep UK interests informed;
- monitor related international and European developments and promulgate them in the UK.

A list of organizations represented on this committee can be obtained on request to its secretary.

Cross-references

The British Standards which implement international or European publications referred to in this document may be found in the *BSI Catalogue* under the section entitled “International Standards Correspondence Index”, or by using the “Search” facility of the *BSI Electronic Catalogue* or of British Standards Online.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

Compliance with a British Standard does not of itself confer immunity from legal obligations.

Summary of pages

This document comprises a front cover, an inside front cover, the EN title page, pages 2 to 59 and a back cover.

The BSI copyright notice displayed in this document indicates when the document was last issued.

This British Standard, having been prepared under the direction of the Electrotechnical Sector Committee, was published under the authority of the Standards Committee and comes into effect on 15 July 1999

© BSI 17 March 2006

ISBN 0 580 32195 9

Amendments issued since publication

Amd. No.	Date	Comments
10697 Corrigendum No. 1	September 1999	Indicated by a sideline
15898 Corrigendum No. 2	March 2006	Revision of supersession details.