

BS EN 61557-9:2015

Incorporating corrigendum January 2017

Licensed copy: University of Manchester Library, The University of Manchester Library, Version corrigendum 1 of 3/10/2020



BSI Standards Publication

Electrical safety in low voltage distribution systems up to 1 000 V a.c. and 1 500 V d.c. — Equipment for testing, measuring or monitoring of protective measures

Part 9: Equipment for insulation fault location in IT systems (IEC 61557-9:2014)

National foreword

This British Standard is the UK implementation of EN 61557-9:2015. It is identical to IEC 61557-9:2014, incorporating corrigendum January 2017. It supersedes BS EN 61557-9:2009 which is withdrawn.

The start and finish of text introduced or altered by corrigendum is indicated in the text by tags. Text altered by IEC corrigendum January 2017 is indicated in the text by AC1 AC1.

The UK participation in its preparation was entrusted to Technical Committee PEL/85, Measuring equipment for electrical and electromagnetic quantities.

A list of organizations represented on this committee can be obtained on request to its secretary.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

© The British Standards Institution 2017.
Published by BSI Standards Limited 2017

ISBN 978 0 580 97636 0

ICS 17.220.20; 25.040.40; 29.080.01

Compliance with a British Standard cannot confer immunity from legal obligations.

This British Standard was published under the authority of the Standards Policy and Strategy Committee on 28 February 2015.

Amendments/corrigenda issued since publication

Date	Text affected
31 March 2017	Implementation of IEC corrigendum January 2017