
**Safety requirements for industrial laundry
machinery —**

Part 6:
Ironing and fusing presses

Exigences de sécurité pour les machines de blanchisserie industrielle —

Partie 6: Presses à repasser et à thermocoller



Contents

	Page
1 Scope	1
2 Normative references.....	1
3 Definitions	2
4 Hazards	3
5 Safety requirements and/or measures for the hazards identified in clause 4.....	4
5.1 General	4
5.2 Mechanical hazards.....	4
5.2.1 Closing and pressing of the head and buck of all presses	4
5.2.2 Operating mechanism of the head and buck of all presses	6
5.2.3 Falling of the head of scissor presses	6
5.3 Electrical hazards	6
5.4 Thermal hazards	6
5.4.1 Hot surfaces of all presses, covered and uncovered.....	6
5.4.2 Free steam affecting the operator (for scissor presses).....	7
5.4.3 Radiated and convected heat affecting the operator (for scissor presses)	7
5.5 Hazards generated by noise	7
5.6 Hazards caused by harmful fumes, for fusing presses	7
5.7 Hazards due to neglect of ergonomic principles in machine design of all presses	7
5.7.1 Inappropriate posture and effort.....	7
5.7.2 Inadequate local lighting	7
5.8 Failure of energy supply or control systems	7
6 Verification of safety requirements and/or measures.....	7
7 Information concerning machine use.....	12
7.1 Instruction handbook	12
7.2 Warning signs	12

© ISO 1997

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization
Case postale 56 • CH-1211 Genève 20 • Switzerland
Internet central@iso.ch
X.400 c=ch; a=400net; p=iso; o=isocs; s=central

Printed in Switzerland