

INTERNATIONAL STANDARD

ISO
11932

First edition
1996-12-15

Activity measurements of solid materials considered for recycling, re-use, or disposal as non-radioactive waste

*Mesures d'activité de matériaux solides considérés comme déchets non
radioactifs destinés à un recyclage, une réutilisation, ou une mise au rebut*

This material is reproduced from ISO documents under International Organization for Standardization (ISO) Copyright License number IHS/ICC/1996. Not for resale. No part of these ISO documents may be reproduced in any form, electronic retrieval system or otherwise, except as allowed in the copyright law of the country of use, or with the prior written consent of ISO (Case postale 56, 1211 Geneva 20, Switzerland, Fax +41 22 734 10 79), IHS or the ISO Licensor's members.



Reference number
ISO 11932:1996(E)

Contents	Page
1 Scope	1
2 Normative references	1
3 Definitions.....	2
4 Requirements for radioactivity measurements related to unrestricted release	3
4.1 General	3
4.2 Surface contamination measurements	3
4.2.1 Radionuclides to be considered	3
4.2.2 Methods to determine surface contamination	4
4.3 Specific activity measurements.....	6
4.3.1 General	6
4.3.2 Measurement techniques	7
4.4 Sampling strategy	9
Annexes	
A Figures for measurements of beta surface contamination	10
B Low-level activity measurements of ⁵⁵ Fe and ⁶³ Ni	12
C Bibliography	18